

Condition report for flood protection and land management assets for all zones

Prepared by:
Rebecca Wheadon

For:
Waikato Regional Council
Private Bag 3038
Waikato Mail Centre
HAMILTON 3240

December 2021

Document #: 20419287

Peer reviewed by:
Lisa Drysdale

Date July 2021

Approved for release by:
Lisa Drysdale

Date July 2021

Disclaimer

This technical report has been prepared for the use of Waikato Regional Council as a reference document and as such does not constitute Council's policy.

Council requests that if excerpts or inferences are drawn from this document for further use by individuals or organisations, due care should be taken to ensure that the appropriate context has been preserved and is accurately reflected and referenced in any subsequent spoken or written communication.

While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this report, Council accepts no liability in contract, tort or otherwise, for any loss, damage, injury or expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you or any other party.

Acknowledgement

Thanks to:

Patu McGee
Gareth Langdon
Steve Hall
Andrew Hoffman
Gill Higgs
Lisa Drysdale

For their assistance in putting this report together.

Table of Contents

| | |
|--|-----------|
| Abstract | iv |
| Executive summary | v |
| 1 Introduction | 1 |
| 1.1 Commonly Used Acronyms | 1 |
| 2 Assets assessment methodology | 2 |
| 2.1 Asset condition general | 2 |
| 2.1.1 Floodgates | 3 |
| 2.1.2 Stopbanks | 3 |
| 2.1.3 Main and Tributary Channels | 4 |
| 2.1.4 Other Assets | 4 |
| 2.2 Asset performance general | 4 |
| 2.2.1 Stopbanks | 4 |
| 3 Our Region at a glance | 6 |
| 3.1 Discussion | 8 |
| 4 Lower Waikato | 9 |
| 4.1 Pumpstations | 9 |
| 4.2 Floodgates | 18 |
| 4.3 Embankments | 31 |
| 4.4 Main Channels and Tributaries | 37 |
| 4.5 Other Assets | 38 |
| 5 Franklin | 40 |
| 5.1 Floodgates | 40 |
| 5.2 Embankments | 40 |
| 6 Waikato Central | 41 |
| 6.1 Pumpstations | 41 |
| 6.2 Floodgates | 42 |
| 6.3 Other Assets | 43 |
| 7 Waihou | 44 |
| 7.1 Pumpstations | 44 |
| 7.2 Floodgates | 46 |
| 7.3 Embankments | 48 |
| 7.4 Main Channels and Tributaries | 49 |
| 7.5 Other Assets | 50 |
| 8 Waihou/Piako Maps | 51 |
| 9 Piako | 59 |
| 9.1 Pumpstations | 59 |
| 9.2 Floodgates | 61 |
| 9.3 Embankments | 65 |
| 9.4 Main Channels and Tributaries | 66 |
| 9.5 Other | 67 |
| 10 Thames Valley | 68 |
| 10.1 Pumpstations | 68 |
| 10.2 Floodgates | 68 |
| 10.3 Embankments | 71 |

| | | |
|-----------|-------------------------------|-----------|
| 10.4 | Other | 71 |
| 11 | Coromandel | 73 |
| 11.1 | Floodgates | 73 |
| 11.2 | Embankments | 74 |
| 11.3 | Main Channels and Tributaries | 75 |
| 11.4 | Other Assets | 76 |
| 12 | Lake Taupo | 77 |
| 12.1 | Floodgate | 77 |
| 12.2 | Embankments | 80 |
| 12.3 | Main Channels and Tributaries | 80 |
| 12.4 | Other Assets | 81 |
| 13 | Waipa | 83 |
| 13.1 | Main Channels and Tributaries | 83 |
| 13.2 | Other Assets | 83 |

Figures

| | | |
|----------|--|---|
| Figure 1 | Performance grading for earth structures | 5 |
|----------|--|---|

Tables

| | | |
|---------|--|---|
| Table 1 | Asset condition grading | 3 |
| Table 2 | Performance grading for earth structures | 4 |

Abstract

This report analyses the data gathered in the field by the council operations staff, mainly by visual observation of assets condition, survey information following annual stopbanks crest level survey by a specialist contractor and any other information that may be available.

The objectives of this report are to:

- Evaluate the physical condition of the assets
- Explain how an asset is performing in relation to design specifications
- Provide an overall assessment in relation to agreed service level performance standard of stopbanks
- Assist relevant Zone Managers and Asset Manager in managing on-going schemes and identifying future work requirements
- Provide basis for reporting to scheme's stakeholders including the scheme's Liaison Subcommittees.

The assets are assessed according to two sets of guidelines. Floodgates and Pumpstations have been assessed using Asset Failure Modes and the asset operating context to assign a Remaining Useful Life Score. Embankments and all other assets have been assessed using the guidelines outlined in the New Zealand Infrastructures Asset Management Manual 1999 and the Condition Assessment Manual 2011 Guidelines for each asset type, adopted by the council. The methodology followed is described in more detail in sections 2 and 2.1.

Collection of field data and information is performed using the Fulcrum Mobile app. Fulcrum is a mobile platform that allows to customise apps to capture field data on iPhone, iPad, and Android devices. The Asset Management team have developed two apps namely, Defect Inspection app and Condition Inspection app. The Defect Inspection app is used to capture defects on stopbanks, licence areas, and channels while the Condition Inspection app is used for floodgates, pumpstations, and other assets.

In general, most of the council's flood protection assets are in a good condition. 93.9% were rated between condition one and three (very good to average), with the other 6.1% rated condition four or five (poor or very poor).

Executive summary

Every year, a combination of external engineers and Waikato Regional Council staff assess the condition of various river structures and flood protection infrastructure, so a condition grading can be assigned, and then used to prioritise future works. These inspections vary in complexity, from dewatering of sites to allow the structural integrity of pumpstations and floodgates to be checked, to the walking or driving of stopbanks looking for bull holes, excessive gorse growth or damaged fences, as examples.

Both the condition of the assets and any defects found, are noted in the asset management system. For the last six years this information has been compiled and analysed annually.

The condition is rated on a one to five scale: very good, good, average, poor, very poor. The type of action that is taken (monitor, minor repairs, complete overhauls, decommission and/or build new) depends on the asset type, the types of defects, and the condition score.

This year 440 floodgates, 108 pumpstations, and 518km of embankments were assessed.

Currently 6.1% of the asset base is considered to be in a poor or very poor condition, whereas last year only 1.5% was in a poor or very poor condition. The assets with poor condition, that have not improved in the last two years include some Lower Waikato Pumpstations and Floodgates and Thames Valley Floodgates.

Current Condition of Assets

In general, most of the council's flood protection assets are in a good condition. 93.9% were rated between condition one and three (very good to average), with the other 6.1% rated condition four or five (poor or very poor).

Of the 6.1% rated condition four or five (poor or very poor), 5.6% deteriorated from last year, with 0.5% having been in poor condition since at least last year. 0.02% of assets improved from being in very poor condition to being in poor condition. Coromandel, Lake Taupo and Waipa all showed minimal or no deterioration, but all other zones showed significant deterioration. Franklin showed the most significant deterioration this year.

Stopbanks

There are 4.2km in Lower Waikato and 8.5km in Piako that are in a poor or unknown condition.

The main issues to rectify with respect to condition of stopbanks are stock damage and vegetation with deep root systems that can affect the integrity of the structure.



Stock Damage - Bull Hole

WRC is seeking to take a more strategic approach to the future management of scheme land by looking at opportunities for improvement. We want to lead by example across our region by promoting sustainable land management practices including improving biosecurity and biodiversity outcomes on scheme land.

The Scheme Land Use Management Plan is aiming to improve scheme land condition and management while balancing the best income options against the cost of management and administration. Protection of flood protection assets and infrastructure will remain a priority for the review.

Pumpstations

We have 13 pumpstations in the Lower Waikato in poor condition, along with 9 in Piako and 1 in Waihou

Other pumpstations across the region have deteriorating component issues, including deteriorating inlets, outlets, pipes and screens.



Mill Road Structural Audit – Waihou Piako Zone

Floodgates

We have 60 floodgates in the Lower Waikato, 16 in Piako, 7 in Waihou and 3 in Thames Valley that are in a poor condition.

Other Asset types

All Assets falling into the “Other” are in average to good condition. There was some deterioration of Poles, Bridges and Control gates, nothing has hit the threshold for being in poor condition.

Conclusion

As a whole, the council assets appear to be in a reasonable condition, however there has been significant deterioration since last year that must be addressed. A number of assets require further attention to decide the best course of action in terms of minimising council risk. Maintenance on all assets must continue to keep them in good condition, and Maintenance programs should be evaluated for their effectiveness.

1 Introduction

This report analyses the data gathered in the field by the Council Operations staff, mainly by visual observation of assets condition, survey information following annual stopbanks crest level survey by a specialist contractor and any other information that may be available.

The objectives of this report are to:

- Evaluate the physical condition of the assets
- Explain how an asset is performing in relation to design specifications
- Provide an overall assessment in relation to agreed service level performance standard of stopbanks
- Assist relevant Zone Managers and Asset Manager in managing on-going schemes and identifying future work requirements
- Provide basis for reporting to scheme's stakeholders including the scheme's Liaison Subcommittees.

1.1 Commonly Used Acronyms

| | |
|-------|--------------------------------------|
| PS | Pumpstation |
| FG | Floodgate |
| SB | Stopbank |
| C(X) | Condition (X), i.e. C5 = Condition 5 |
| RUSL | Remaining Useful Service Life |
| DQR | Data Quality Rating |
| SLUMP | Scheme Land Use Management Plan |

2 Assets assessment methodology

Traditionally, annual asset condition grading has been resourced by operations staff in their respective areas. Each year 6 to 12 Inspectors provide the condition grades across the WRC Flood protection/drainage asset base. To assist with this in 2011, WRC developed a condition Manual that was written loosely around the New Zealand Infrastructure Asset Management Manual 1999. Despite this, consistent condition grading has long been a problem; recently questions have been asked around it being fit for purpose and the effectiveness of training for Inspectors to promote consistency of condition grading.

To combat these issues, this year the Pumpstations and Floodgates in Lower Waikato, Franklin, Waikato Central, Waihou, Piako and Thames Valley were assessed by just 1 person - the Reliability Engineer from the Asset Management Team. These inspections focused on Asset Failure Modes and the asset operating context which produce a much more realistic score. This has resulted in some shifts in condition that may not have been seen if the inspections had been carried out to the traditional standard. The scores are determined by Remaining Useful Service Life:

| | |
|----|---|
| C1 | >75% RUSL (Remaining Useful Service Life) |
| C2 | 34 to 74% RUSL |
| C3 | 13 to 33% RUSL |
| C4 | 5 to 12% RUSL |
| C5 | <5% RUSL |

i.e., if standard life is 80 years, a score of 4 would indicate 4 to 10 years left, while a score of 5 would indicate it is into the last 4 years of useful life.

The intention going forward is to formalise this standard and update the condition manual to ensure it is adhered to in the future. Additional work should also be done to reflect all stakeholders; It is conceivable that an asset may be a condition 1 from an operational point of view but a 4 from an environmental point of view, a distinction that this standard does not allow for.

Each component is assessed, and the condition of the components is considered when determining the condition of a parent asset.

The methodology followed for all other assets (including Floodgates in Coromandel and Lake Taupo) is described below.

2.1 Asset condition general

This part of the report is a summary of information derived from visual inspections undertaken by Council staff during the year. Each asset type is inspected, assessed, and graded based on the typical physical condition. The asset condition grading system is shown in Table 1. The assets that are visually inspected include:

- Stopbanks
- Floodgates
- Pumpstations
- Channels
- Other Assets (groynes, culverts, weirs etc.)

Collection of field data and information is performed using the Fulcrum Mobile app. Fulcrum is a mobile platform that allows to customise apps to capture field data on iPhone, iPad, and Android devices.

The Asset Management team have developed two apps namely, Defect Inspection app and Condition Inspection app. The Defect Inspection app is used to capture defects on stopbanks, licence areas, and channels while the Condition Inspection app is used for floodgates, pumpstations, and other assets.

| Grade | Condition | Condition measure |
|-------|------------------------------|---|
| 1 | Near new condition | Asset has recently been built/upgraded, very good condition |
| 2 | Normal maintenance required | Good condition, continue with routine maintenance |
| 3 | Backlog maintenance required | Average condition, non-routine maintenance required |
| 4 | Major renewal required | Poor condition, urgent maintenance required |
| 5 | Asset unserviceable | Very poor condition, needs replacement/urgent upgrade |

Table 1 Asset condition grading

2.1.1 Floodgates

Floodgates are also visually inspected every year by Council’s Operations staff. Field data such as photographs, attribute information and asset location, are collected using the customised Fulcrum Condition Inspection app.

Each component of the floodgate is inspected, assessed and graded using the criteria described in Table 1. Each floodgate is given an overall condition grade taking into account the grade of each component.

2.1.2 Stopbanks

Stopbanks condition assessment is done for the entire stopbank. Using the Defect Inspection app, the inspector walks or drives along the stopbank, captures and re-inspects every defect of the stopbank. Dependant on the number and degree of the captured defects, the inspector scores the stopbank using the scale shown in Table 1. The overall scoring is based on the following factors:

- Vegetation cover
- Embankment erosion
- Damage (stock, vehicles, etc.)
- Geometry (shape)
- Berm erosion



2.1.3 Main and Tributary Channels

The Main and Tributary Channels of Lower Waikato River are visually inspected annually by Council Operations staff. Identical to stopbank inspections, Fulcrum Defect Inspection app is used to record information and capture defects along each channel reach.

Any signs of bank erosion, sediment build-up, fallen trees and other damage or obstructions to flow are noted. Stock damage in unfenced areas along the Main Channel is also noted.

Every captured defect is assessed and graded using the asset condition grading in Table 1. The overall condition scoring is based on the number and degree of defects and judgment of the inspector.

2.1.4 Other Assets

Other assets such as control gates, weirs, bridges, etc. are also visually inspected every year by Council Operations staff. The inspection and grading procedures are similar to floodgates and pumpstations.

2.2 Asset performance general

Asset performance is a measure of an asset's ability to perform to design standards and to provide the level of service it was designed for. For this purpose, investigations, surveys and specific technical data are required for performance assessment of each asset type. Performance values are measured on a similar scale to the condition values, however, the criteria differs, as explained further.

The asset performance being assessed include:

- Stopbanks and spillways
- Floodgates
- Pumpstations

In addition, following a flood event the whole flood protection scheme affected is assessed against the design standard.

2.2.1 Stopbanks

The performance of a stopbank is assessed by comparing the current crest level against the Design Crest Level (DCL). The assessment is done at every 100m length or link of stopbank, where the calculated current lowest crest level is compared to DCL.

Each link is assessed and graded applying the criteria set out in Table 2. The lowest grade of any link of the stopbank represents the overall performance grade of the stopbank.

| Crest level results | |
|---------------------|--|
| Grade | Crest level measure |
| 1 | Actual crest level > design bank level @100% |
| 2 | Actual crest level > target level @100% |
| 3 | Actual crest level < target level at any point |
| 4 | Actual crest level < half (target level + design flood level) at any point |
| 5 | Actual crest level < design flood level at any point |

Table 2 Performance grading for earth structures

This table can be graphically presented:




Figure 1 Performance grading for earth structures

Legend:


DFL is the Design Flood Level

DCL is the Design Crest Level, which is DFL plus the freeboard

Target is the target level, which is $DFL + \frac{1}{2}$ of freeboard

Therefore, a performance grade 1 is given to a stopbank link with the current minimum crest level above DCL; performance grade 2 for link with current crest level between DCL and Target level.


Stopbank section that has lost between half and three-quarters of the freeboard gets a performance grade 3, while those that lost three-quarters or all of the freeboard receives grade 4. Performance grade 5 is for link with current crest level below DFL.




3 Our Region at a glance

| | Embankments | | Floodgates | | Pumpstations | | Rivers and Streams | | Other Assets | |
|-----------------|-------------|-------|------------|-------|--------------|-------|--------------------|-------|--------------|-------|
| | Total | C4/C5 | Total | C4/C5 | Total | C4/C5 | Total | C4/C5 | Total | C4/C5 |
| Franklin | 5km | 0km | 1 | 0 | | | | | | |
| Coromandel | 2km | 0km | 5 | 0 | | | 43km | 0km | 19 | 0 |
| Lower Waikato | 202km | 4km | 265 | 61 | 59 | 13 | 134km | 0km | 97 | 0 |
| Waihou | 164km | 0km | 69 | 7 | 19 | 1 | 462km | 0km | 74 | 0 |
| Piako | 133km | 9km | 60 | 16 | 28 | 9 | 362km | 0km | 20 | 0 |
| Waipa | | | | | | | 10km | 0km | 1 | 0 |
| Waikato Central | | | 6 | 0 | 2 | 0 | | | 20 | 0 |
| Thames Valley | 4km | 0km | 11 | 3 | 1 | 0 | | | 29 | 0 |
| Lake Taupo | 8km | 0km | 23 | 0 | | | 213km | 0km | 35 | 0 |


Percentage of Region-wide Pumpstations at each Condition




Percentage of Region-wide Floodgates at each Condition



Percentage of Region-wide Embankments at each Condition



Percentage of Region-Wide Main Channels and Tributaries at each Condition



3.1 Discussion

It is obvious from looking at the charts above that Pumpstations and Floodgates are where a number of problems lie. Ideally we would prefer to see 95% of assets be in a very good to average condition, with the remaining 5% being already in the pipeline for remedial works. In this situation, C4/5 assets would be in the scope/design/build phase and C3 assets would make up most of the 10-year Long Term Plan.

With approximately 20% of Pumpstations and Floodgates in poor to very poor condition, there is clearly a shortfall in how we manage these asset types. Maintenance programs need to be evaluated to look at what value we get for our investments, as well as carried out more collaboratively with other parts of the organisation. A capital works program driven by this report where the degrading assets were prioritised would also cause a rise in overall condition, provided the works can be done to a rigorous standard with a full scoping and quality control component.


Annual Condition Inspections need to be carried out with rigour and attention to detail; with special attention paid to the Data Quality Rating. Having good data with a well understood level of uncertainty will assist in build the right capital works program to address the most critical assets.

4 Lower Waikato

4.1 Pumpstations


58 Pumpstations were inspected in Lower Waikato as part of the condition monitoring program this year. Of these, 77.6% were found to be in a good to average condition, with 22.4% (or 13 Pumpstations) found to be in poor condition.

As the condition of a Pumpstation is determined by the poorest condition component, further discussion of the components is required. Pumpstation Inlet Bays are the component most commonly in a poor condition, with 15% of all inlets being graded at condition 4, or 9 individual assets. Outlets are also a common mode of failure. This represents a large risk to the operational effectiveness of the pumpstation network.




| | No Change | Deteriorated | Improved |
|--------------|-----------|--------------|----------|
| PS Component | 76.0% | 17.8% | 6.2% |
| Pumpstation | 37.6% | 55.9% | 6.5% |

In terms of condition change, all Gearboxes and Hydraulic Pumps and 75% of Grille Screens were found to have deteriorated since last year, whilst 71% of Concrete and Sheet Pile Sumps and 50% of Screw Pumps have improved on last year's rating.



Pumpstation Average Condition has remained relatively stable over the last six years, although the overall average condition is the among the highest in the zone; almost all other asset types in Lower Waikato are in better condition than the Pumpstations and their components. As discussed in section 4.1, Pumpstations are poorly managed region wide and further investigation is required as to where improvements can be made.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.

Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology


Pumpstation Condition map.
2020-21
ICM Zone: Lower Waikato (western) Sub Zone Area (labelled)



Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114_



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology


Pumpstation Condition map.
2020-21
ICM Zone: Lower Waikato (eastern)
Sub Zone Area (labelled)



Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.

Condition data provided by ICM - Hyperion report.

Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology

Pumpstation Condition map.

2020-21

ICM Zone: Lower Waikato (eastern)
 Work Supervisor Area (labelled)




Scale at A4
 = 1:200,000

Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise howsoever, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management
 Boundaries Data.

Condition data provided by ICM - Hyperion report.

Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth,
 © OpenStreetMap contributors, LINZ, Eagle Technology

Pumpstation Condition Change map.

2020-21

ICM Zone: Lower Waikato (western)




Scale at A4
 = 1:200,000

Created by: AJH
 Date: 27/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology

Pumpstation Condition Change map.
2020-21
ICM Zone: Lower Waikato (eastern)



Created by: AJH
 Date: 27/05/2021
 Version: 1
 File: RED173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise howsoever, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.

A list of both parent and child assets in a poor condition is shown below. As a rule, the parent asset (a pumpstation in this case) is determined by the worst condition component. However, there are some components that have very little impact on the running of the Pumpstation as a

whole and therefore should not influence the score. For example, the screen on Airey's PS is a C5, but Aireys PS as an Asset was judged by the inspector to be a C3.

The assets below should be prioritised in any upcoming capital works programme as the present an urgent risk to the safe operating of the assets.

| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change | Current Inspection Notes |
|---|---------------------------|-------------------------|-------------------------|------------------|--|
| Hills Pumpstation | Pumpstation: Throughbank | 2 | 4 | 2 | |
| Guests Pumpstation | Pumpstation: Throughbank | 2 | 4 | 2 | |
| Saxton Pumpstation (Comins) | Pumpstation: Throughbank | 2 | 4 | 2 | |
| Pattersons (Horohoro) Pumpstation | Pumpstation: Throughbank | 1 | 4 | 3 | |
| Harveys Pumpstation | Pumpstation: Throughbank | 2 | 4 | 2 | |
| Motukaraka Pumpstation Duty Pump (Mac Ewans) | Pumpstation: Siphon Flood | 2 | 4 | 2 | Inlet retaining |
| Rangiriri North Pumpstation | Pumpstation: Throughbank | 2 | 4 | 2 | Outlet sheetpiling |
| Churchill East Watts Pumpstation | Pumpstation: Throughbank | 2 | 4 | 2 | Outlet issues |
| Island Block North Secondary Pumpstation (Pump 1) | Pumpstation: Throughbank | 2 | 4 | 2 | |
| Sandy Muirs Pumpstation | Pumpstation: Throughbank | 4 | 4 | 0 | Inlet issued |
| Mangawhero Pumpstation Lower Waikato | Pumpstation: Throughbank | 4 | 4 | 0 | Needs major works |
| Mangatawhiri Compartment 2 Pumpstation | Pumpstation: Throughbank | 3 | 4 | 1 | Outlet retaining |
| Mangatawhiri Compartment 3 Pumpstation Duty Pump | Pumpstation: Throughbank | 3 | 4 | 1 | Inlet sump screen issues |
| Components: | | | | | |
| Huntly North PS - Inlet Channel Rip Rap | Lined Channel: Rip Rap | 1 | 4 | 3 | No steel in it. Very thin and vegetation breaking through it |
| Huntly South PS/FG 3 - Screen | Screen: Bar | 2 | 4 | 2 | Rusted out |
| Huntly South PS/FG 3 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Lots of cracks and gaps to repair |
| Hills PS - Discharge Pipe 2 | Pipework | 2 | 4 | 2 | Pipe leaking underground water flowing through concrete wall |
| Guests PS - Inlet Structure | Pumpstation Inlet Bay | 2 | 4 | 2 | Retaining issues |
| Saxton PS - Inlet Structure | Pumpstation Inlet Bay | 3 | 4 | 1 | Sheetpiling failing |
| Pattersons PS - Inlet Bay | Pumpstation Inlet Bay | 2 | 4 | 2 | Sheetpiling failed |
| Harveys PS - Inlet Structure | Pumpstation Inlet Bay | 2 | 4 | 2 | Retaining wall failed |
| Orton PS - Motor 2 | Motors | 2 | 4 | 2 | Axial wear |

| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change | Current Inspection Notes |
|---|---------------------------------------|-------------------------|-------------------------|------------------|--|
| Motukaraka PS: Duty Pump - Inlet Structure | Pumpstation Inlet Bay | 3 | 4 | 1 | Failing |
| Rangiriri North PS - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Sheetpiling looks very rusty and close to end of life |
| Churchill East PS - Pump and Motor 3 | Pump: Axial Submersible | 2 | 4 | 2 | Pump end of life |
| Churchill East PS - Pump and Motor 2 | Pump: Axial Submersible | 2 | 4 | 2 | Pump end of life |
| Churchill East Watts PS - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Major cracks and retaining wall undermined |
| Churchill East Watts PS - Flapvalve Gravity | Valve: Flap Round | 2 | 4 | 2 | Very rusty |
| Meremere Main PS - Screen | Screen: Bar | 2 | 4 | 2 | Rusted and broken |
| Island Block North Secondary PS - Discharge Pipe | Pipework | 2 | 4 | 2 | Circumferential cracks, root intrusion and dipped from 2019 cctv |
| Island Block North Secondary PS - Inlet Structure | Pumpstation Inlet Bay | 2 | 4 | 2 | Timber retaining has failed |
| Island Block North Secondary PS - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Trees removed around outlet but concrete headwall is majorly cracked |
| Sandy Muirs PS - Screen | Screen: Bar | 4 | 4 | 0 | Rusted |
| Sandy Muirs PS - Inlet Structure | Pumpstation Inlet Bay | 4 | 4 | 0 | Poor construction |
| Mangawhero PS - Pump Building | Building: Corrugated Iron | 4 | 4 | 0 | Needs rebuilt |
| Mangawhero PS - Outfall Structure | Outlet Structure | 4 | 4 | 0 | End of life |
| Mangawhero PS - Screen | Screen: Grille | 3 | 4 | 1 | Very rusty |
| Mangawhero PS - Inlet Structure | Pumpstation Inlet Bay | 4 | 4 | 0 | End of life |
| Aireys PS - Screen | Screen: Bar | 3 | 5 | 2 | End of life |
| Tuakau PS/FG - Screen (Inlet) | Screen: Grille | 4 | 5 | 1 | Broken |
| Mangatawhiri Compartment 2 PS - Outfall Structure | Outlet Structure | 3 | 4 | 1 | Retaining failed |
| Mangatawhiri Compartment 2 PS - Screen | Screen: Bar | 3 | 4 | 1 | Rusted |
| Mangatawhiri Comp 2 PS (submersible) - Outfall Structure | Outlet Structure | 3 | 4 | 1 | Rebuild timber structure |
| Mangatawhiri Compartment 3 PS Duty Pump - Screen | Screen: Bar | 3 | 5 | 2 | Horrendous |
| Mangatawhiri Compartment 3 PS Duty Pump - Sump | Sump: Reinforced Concrete Rectangular | 3 | 4 | 1 | Horrendous |
| Mangatawhiri Compartment 3 PS Duty Pump - Inlet Structure | Pumpstation Inlet Bay | 3 | 4 | 1 | Horrendous |
| Mangatawhiri Compartment 3 PS Duty Pump - Pump | Service Beam | 4 | 4 | 0 | Same as the screw pump |

| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change | Current Inspection Notes |
|--|--------------------------|-------------------------|-------------------------|------------------|--------------------------|
| Access Platform and Shelter | | | | | |
| Mangatawhiri Compartment 4 Main PS - Switchboards and Controls | Switchboard and Controls | 4 | 4 | 0 | Rusting and very old |


4.2 Floodgates

264 Floodgates were inspected in the Lower Waikato this year, of these 77.3% were found to be in average to good condition, with the remaining 22.8% in poor condition.


Looking at the Floodgate components, Pipes and Outlets were the assets most commonly in a poor condition, with 13% and 16% respectively scoring condition 4 or 5. This amounts to 34 pipes and 27 outlets. Pipes and Outlets were also the most likely to have deteriorated from last year with 32% of pipes and 42% of outlets showing worse condition since last year.

These two statistics combined suggest that pipes and outlets could be the most impacted by the new condition scoring method detailed section 3, but that does not diminish the risk posed by this information. Damaged pipes and outlets present serious operational challenges.

The most improved asset type was Cable and Winch Lifting Gear of which 63% improved over last year.




Percentage of FG Components at each Condition




| | No Change | Deteriorated | Improved |
|--------------|-----------|--------------|----------|
| FG Component | 68.2% | 25.0% | 6.8% |
| Floodgate | 46.3% | 46.0% | 7.7% |

Floodgate Average Condition Over Time



Floodgate Average Condition shows a moderate rise this year as compared to the stability of the last 5 years. Possible factors in this could include:

- The new scoring system
- The impact of multiple Auckland Lockdowns on the northern parts of the region
- A genuine degradation of these assets



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology


Pumpstation Condition map.
2020-21
ICM Zone: Lower Waikato (western)
Work Supervisor Area (labelled)



Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management
 Boundaries Data.

Condition data provided by ICM - Hyberton report.

Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth,
 © OpenStreetMap contributors, LINZ, Eagle Technology

Pumpstation Condition map.

2020-21

**ICM Zone: Lower Waikato (eastern)
 Work Supervisor Area (labelled)**




Scale at A4
 = 1:200,000

Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise
 however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management
 Boundaries Data.

Condition data provided by ICM - Hypercent report.

Eagle Technology, LINZ, StateNZ, NIWA, Natural Earth,
 © OpenStreetMap contributors, LINZ, Eagle Technology

Floodgate Condition map.

2020-21

**ICM Zone: Lower Waikato (western)
 Work Supervisor Area (labelled)**




Scale at A4
 = 1:200,000

Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise
 however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.

Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology


Floodgate Condition map.
2020-21
ICM Zone: Lower Waikato (eastern)
Work Supervisor Area (labelled)



Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise howsoever, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology


Floodgate Condition Change map.
2020-21
ICM Zone: Lower Waikato (western)



Created by: AJH
 Date: 27/05/2021
 Version: 1
 File: REQ173114_



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StateNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology

Floodgate Condition Change map.
2020-21
ICM Zone: Lower Waikato (eastern)



Created by: AJH
 Date: 27/05/2021
 Version: 1
 File: REQ173114_



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.

A list of both parent and child assets in a poor condition is shown below. As a rule, the parent asset (a floodgate in this case) is determined by the worst condition component.

The assets below should be prioritised in any upcoming capital works programme as the present an urgent risk to the safe operating of the assets.

| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change Raw | Current Inspection Notes |
|--|-------------------------|-------------------------|-------------------------|----------------------|---------------------------------|
| Floodgate 02/04 (3 x 1200mm) | Floodgate: Conventional | 3 | 4 | 1 | Outlet concrete issues |
| Floodgate 02/13 (1200mm) | Floodgate: Conventional | 2 | 4 | 2 | Outlet and pipe issues |
| Comp 2 Rutherford Drain Right Bank Floodgate (450mm) | Floodgate: Conventional | 4 | 4 | 0 | Outlet issues |
| Floodgate 03/06 (300mm) | Floodgate: Conventional | 4 | 4 | 0 | Pipe issues |
| Floodgate 03/24 (300mm) | Floodgate: Conventional | 2 | 4 | 2 | Pipe issues |
| Floodgate 04/12 (300mm) | Floodgate: Conventional | 3 | 5 | 2 | Inlet issues |
| Floodgate 04/33 (600mm) | Floodgate: Conventional | 2 | 4 | 2 | Outlet failed |
| Floodgate 05/06 (2 x 1200mm) | Floodgate: Conventional | 2 | 4 | 2 | Pipe issues |
| Floodgate 05/13 (600mm) | Floodgate: Conventional | 2 | 4 | 2 | Outlet issues |
| Floodgate 05/14 (300mm) | Floodgate: Conventional | 2 | 4 | 2 | Pipe and outlet issues |
| Floodgate 05/21 (450mm) | Floodgate: Conventional | 2 | 4 | 2 | Pipe and flap |
| Floodgate 05/23 (450mm) | Floodgate: Conventional | 2 | 4 | 2 | Pipe and outlet issues |
| Floodgate 05/24 (450mm) | Floodgate: Conventional | 3 | 4 | 1 | Pipe issues |
| Floodgate 05/28 (450mm) (Sludge Creek) | Floodgate: Conventional | 1 | 4 | 3 | Pipe issues |
| Floodgate 05/30 (450mm) (Sludge Creek) | Floodgate: Conventional | 3 | 4 | 1 | Pipe |
| Floodgate 05/32 (300mm) Sludge Creek | Floodgate: Conventional | 2 | 4 | 2 | Outlet and flap issues |
| Floodgate 05/38 (Henrys Remedial Outlet Drain LB) | Floodgate: Conventional | 2 | 4 | 2 | Pipe issues |
| Floodgate 06/06 (450mm) Tauhei Diversion | Floodgate: Conventional | 2 | 4 | 2 | Pipe issues |
| Floodgate 06/08 (600mm) (Tauhei Diversion) | Floodgate: Conventional | 2 | 4 | 2 | Outlet |
| Floodgate 06/11 (300mm) (Mangawara River) | Floodgate: Conventional | 2 | 4 | 2 | Pipe concerning |
| Floodgate 06/12 (300mm) (Mangawara River) | Floodgate: Conventional | 2 | 5 | 3 | Partially decommissioned |
| Floodgate 07/04 (300mm) (Sludge Creek) | Floodgate: Conventional | 2 | 4 | 2 | Pipe sag |
| Floodgate 07/05 (900mm) (Sludge Creek) | Floodgate: Conventional | 3 | 4 | 1 | Outlet and possibly pipe issues |
| Floodgate 07/10 (300mm) (Mangawara River) | Floodgate: Conventional | 2 | 4 | 2 | Pipe sag |
| Floodgate 07/12 (750mm) (Mangawara River) | Floodgate: Conventional | 3 | 4 | 1 | Outlet knackered |
| Floodgate 07/15 (300mm) (Mangawara River) | Floodgate: Conventional | 2 | 4 | 2 | Outlet issues |
| Floodgate 07/16 (600mm) (Mangawara River) | Floodgate: Conventional | 2 | 4 | 2 | Pipe misaligned |
| Floodgate 07/17 (300mm) (Mangawara River) | Floodgate: Conventional | 2 | 4 | 2 | Outlet issues |
| Floodgate 08/11 (450mm) (Mangawara River) | Floodgate: Conventional | 2 | 4 | 2 | Pipe |
| Floodgate 09/15 (300mm) (Mangawara River) | Floodgate: Conventional | 2 | 4 | 2 | Pipe |

| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change Raw | Current Inspection Notes |
|--|-------------------------|-------------------------|-------------------------|----------------------|------------------------------|
| Floodgate 09/19 (300mm) (Paranui Drain) | Floodgate: Conventional | 2 | 4 | 2 | Pipe |
| Floodgate 09/21 (300mm) (Paranui Drain) | Floodgate: Conventional | 2 | 4 | 2 | Outlet and pipe |
| Floodgate 09/23 (300mm) (Paranui Drain) | Floodgate: Conventional | 4 | 4 | 0 | Outlet and pipe failed |
| Floodgate 09/26 (300mm) Paranui Drain | Floodgate: Conventional | 3 | 4 | 1 | Pipe |
| Floodgate 09/29 (Paranui Drain Clarkes) | Floodgate: Conventional | 2 | 4 | 2 | Pipe |
| Floodgate 10/06 (300mm) Mangawara River | Floodgate: Conventional | 3 | 4 | 1 | Pipe |
| Floodgate 10/07 (1600mm) (Mangawara River) | Floodgate: Conventional | 2 | 4 | 2 | Outlet and flap issues |
| Floodgate 12/09 (450mm) (Paranui Drain) | Floodgate: Conventional | 2 | 4 | 2 | All |
| Floodgate 12/10 (750mm) (Paranui Drain) | Floodgate: Conventional | 2 | 4 | 2 | Outlet |
| Floodgate 13/16 (300mm) | Floodgate: Conventional | 3 | 4 | 1 | Pipe failed |
| Floodgate 13/18 (300mm) | Floodgate: Conventional | 4 | 4 | 0 | Pipe failed |
| Floodgate 20/03 (300mm) Tauhei Left Bank | Floodgate: Conventional | 2 | 4 | 2 | Pipe failed |
| Floodgate 20/04 (300mm) Tauhei Left Bank | Floodgate: Conventional | 2 | 4 | 2 | Can't see through pipe |
| Floodgate 21/05 (375mm) Tauhei Scheme Right Bank | Floodgate: Conventional | 2 | 5 | 3 | Flap failed |
| Floodgate 22/04 (375mm) Tauhei Scheme Right Bank | Floodgate: Conventional | 2 | 4 | 2 | Pipe failed |
| Floodgate 22/06 (375mm) Tauhei Scheme Right Bank | Floodgate: Conventional | 2 | 4 | 2 | Pipe suspect and flap failed |
| Floodgate 24/02 (600mm)(Tauhei Mangatea Stream) | Floodgate: Conventional | 2 | 4 | 2 | Flap failed |
| Floodgate 24/04 (600mm) Tauhei Mangatea Stream | Floodgate: Conventional | 4 | 4 | 0 | Needs new flap |
| Morrison Road Floodgate 06 RB | Floodgate: Conventional | 3 | 4 | 1 | Outlet failed |
| Morrison Road Floodgate 07 LB | Floodgate: Conventional | 3 | 4 | 1 | Outlet failed |
| Morrison Road Floodgate 11 LB | Floodgate: Conventional | 4 | 4 | 0 | Outlet and pipe issues |
| Morrison Road Floodgate 13 LB | Floodgate: Conventional | 3 | 4 | 1 | Outlet |
| Morrison Road Floodgate 16 RB | Floodgate: Conventional | 5 | 5 | 0 | Lost outlet |
| Northern Compartment Downstream Floodgate | Floodgate: Conventional | 2 | 4 | 2 | Pipe failed |
| Kimihia Upstream Floodgate | Floodgate: Conventional | 2 | 4 | 2 | Inlet issues |
| Kimihia Main Outlet Floodgate | Floodgate: Conventional | 2 | 4 | 2 | Outlet sheetpiling failing |
| Hoods Landing Minor Floodgate | Floodgate: Conventional | 5 | 5 | 0 | Knackered |
| Hair Floodgate | Floodgate: Conventional | 2 | 4 | 2 | Flap and pipe issues |
| Volz Floodgate | Floodgate: Conventional | 4 | 4 | 0 | Outlet issues |
| Liefting Floodgate | Floodgate: Conventional | 3 | 5 | 2 | Needs investigation |
| Components: | | | | | |


| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change Raw | Current Inspection Notes |
|--|-------------------|-------------------------|-------------------------|----------------------|------------------------------------|
| FG 02/04 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Possibly major concrete issues |
| FG 02/13 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Headwall failed |
| FG 02/13 - Flapvalve | Valve: Flap Round | 2 | 4 | 2 | New hangers etc |
| FG 02/14A - Flapvalve | Valve: Flap Round | 3 | 4 | 1 | Repair or replace |
| FG 02/18 - Flapvalve | Valve: Flap Round | 2 | 4 | 2 | Flap seized |
| Comp 2 Rutherford Drain RB FG - Outlet Structure | Outlet Structure | 4 | 4 | 0 | Outlet |
| FG 03/10 - Rock Outlet | Outlet Structure | 4 | 4 | 0 | Rock mostly gone |
| FG 03/15 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Rebuild rock outlet |
| FG 03/24 - Pipe | Barrel: Pipe | 2 | 4 | 2 | Pipe issues |
| FG 04/12 - Pipe | Barrel: Pipe | 2 | 5 | 3 | Inlet covered over |
| FG 04/33 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Cracked |
| FG 05/06 - Discharge Pipe 1 | Barrel: Pipe | 2 | 4 | 2 | Pipes separating |
| FG 05/13 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Outlet failed |
| FG 05/14 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Cracking |
| FG 05/14 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Can see no light thru pipe |
| FG 05/21 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Pipe bent hugely and holding water |
| FG 05/21 - Flapvalve | Valve: Flap Round | 2 | 5 | 3 | Fallen off hangers |
| FG 05/23 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Holding water |
| FG 05/23 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Crack |
| FG 05/24 - Pipe | Barrel: Pipe | 2 | 4 | 2 | Separating and holding water |
| FG 05/28 - Discharge Pipe | Barrel: Pipe | 1 | 4 | 3 | Pipe issues |
| FG 05/30 - Pipe | Barrel: Pipe | 2 | 4 | 2 | Issues |
| FG 05/32 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Collapsed |
| FG 05/32 - Flapvalve | Valve: Flap Round | 2 | 4 | 2 | End of life |
| FG 05/38 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Pipe issues |
| FG 06/06 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Pipe separated |
| FG 06/08 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Cracks |
| FG 06/11 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Can't see through it |
| FG 06/11 - Flapvalve | Valve: Flap Round | 2 | 5 | 3 | End of life |
| FG 07/04 - Pipe | Barrel: Pipe | 2 | 4 | 2 | Sag |
| FG 07/05 - Outlet Structure | Outlet Structure | 3 | 4 | 1 | Many issues |
| FG 07/09 - Flapvalve | Valve: Flap Round | 3 | 4 | 1 | Rusted |
| FG 07/10 - Pipe | Barrel: Pipe | 2 | 4 | 2 | Sagged |
| FG 07/12 - Outlet | Outlet Structure | 3 | 4 | 1 | End of life |
| FG 07/15 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Cracking |

| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change Raw | Current Inspection Notes |
|--|-------------------|-------------------------|-------------------------|----------------------|---|
| FG 07/16 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Pipe misaligned |
| FG 07/17 - Outlet | Outlet Structure | 2 | 4 | 2 | Outlet damage |
| FG 08/11 - Pipe | Barrel: Pipe | 2 | 4 | 2 | Sagging and last section has separated |
| FG 09/15 - Pipe | Barrel: Pipe | 2 | 4 | 2 | Pipe cannot see through |
| FG 09/19 - Pipe | Barrel: Pipe | 2 | 4 | 2 | Blocked pipe |
| FG 09/21 - Outlet | Outlet Structure | 2 | 4 | 2 | Cracked |
| FG 09/21 - Pipe | Barrel: Pipe | 2 | 4 | 2 | Blocked |
| FG 09/23 - Pipe | Barrel: Pipe | 2 | 4 | 2 | Very sagged |
| FG 09/23 - Outlet | Outlet Structure | 3 | 4 | 1 | Snapped |
| FG 09/25 - Flapvalve | Valve: Flap Round | 2 | 4 | 2 | Cracked |
| FG 09/26 - Discharge Pipe | Barrel: Pipe | 3 | 4 | 1 | Misaligned sections |
| FG 09/29 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Pipe misalignment |
| FG 10/06 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Totally blocked cannot see anything but black |
| FG 10/07 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Holes in concrete |
| FG 10/07 - Flapvalve | Valve: Flap Round | 2 | 4 | 2 | Loose on pipe |
| FG 12/09 - Outlet | Outlet Structure | 2 | 4 | 2 | Concrete issues |
| FG 12/09 - Pipe | Barrel: Pipe | 2 | 4 | 2 | Can't see through it |
| FG 12/09 - Valve | Valve: Flap Round | 2 | 4 | 2 | Rusty |
| FG 12/10 - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Concrete failing |
| FG 13/16 - Discharge Pipe | Barrel: Pipe | 3 | 4 | 1 | Pipe failed |
| FG 13/18 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Pipe failed |
| FG 20/03 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Pipe failed |
| FG 20/04 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Can't see through pipe |
| FG 21/05 - Flapvalve | Valve: Flap Round | 2 | 5 | 3 | Section missing |
| FG 22/04 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Pipe failed |
| FG 22/06 - Flapvalve | Valve: Flap Round | 2 | 5 | 3 | Rusted out |
| FG 23/03 - Flapvalve | Valve: Flap Round | 3 | 4 | 1 | Rusted |
| FG 24/02 - Flapvalve | Valve: Flap Round | 2 | 4 | 2 | Rusted |
| FG 24/04 - Flapvalve | Valve: Flap Round | 4 | 5 | 1 | Flap rusting away |
| Morrison Road FG 04 - Flapvalve 2 | Valve: Flap Round | 4 | 4 | 0 | End of life |
| Morrison Road FG 06 - Outlet Structure | Outlet Structure | 3 | 4 | 1 | Outlet failed |
| Morrison Road FG 07 - Outlet Structure | Outlet Structure | 4 | 4 | 0 | Rebuild |
| Morrison Road FG 11 - Discharge Pipe | Barrel: Pipe | 4 | 4 | 0 | Investigate pipe appears to have failed |
| Morrison Road FG 11 - Outlet Structure | Outlet Structure | 4 | 4 | 0 | Failed |
| Morrison Road FG 13 - Flapvalve | Valve: Flap Round | 4 | 4 | 0 | Replace |

| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change Raw | Current Inspection Notes |
|---|-------------------|-------------------------|-------------------------|----------------------|---|
| Morrison Road FG 13 - Outlet Structure | Outlet Structure | 3 | 4 | 1 | Rebuild |
| Morrison Road FG 14 - Flapvalve | Valve: Flap Round | 3 | 4 | 1 | Replace flap |
| Morrison Road FG 15 - Flapvalve | Valve: Flap Round | 3 | 4 | 1 | Replace |
| Morrison Road FG 16 - Discharge Pipe | Barrel: Pipe | 2 | 4 | 2 | Outlet blocked and lost |
| Northern Compartment Downstream FG - Discharge Pipe | Barrel: Pipe | 3 | 4 | 1 | Failed |
| Kimihia Upstream FG - Inlet Structure | Inlet Structure | 2 | 4 | 2 | Broken cracked concrete and exposed rebar |
| Kimihia Main Outlet FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Sheetpiling failing |
| Papa FG - Flapvalve | Valve: Flap Round | 3 | 4 | 1 | End of life |
| Hoods Landing Minor FG - Discharge Pipe | Barrel: Pipe | 2 | 5 | 3 | Under water at low tide |
| Hoods Landing Minor FG - Flapvalve | Valve: Flap Round | 5 | 5 | 0 | Jammed closed very rusted |
| Hair FG - Discharge Pipe | Barrel: Pipe | 3 | 4 | 1 | Can see no light |
| Hair FG - Flapvalve | Valve: Flap Round | 2 | 4 | 2 | Flap knackered |
| Volz FG - Outfall Structure | Outlet Structure | 5 | 4 | -1 | Timber resting and headwall failing |
| Snook FG - Flapvalve | Valve: Flap Round | 3 | 4 | 1 | End of life soon |
| Liefting FG - Flapvalve | Valve: Flap Round | 4 | 5 | 1 | End of life |
| Liefting FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Concrete disintegrated |

4.3 Embankments


Of the 202km of embankments surveyed this year 97.9% was found to be in average to good condition, with vegetation, stock damage and missing fences being the main issues raised in the inspection notes.




| | Deteriorated | Improved | No Change |
|-------------|--------------|----------|-----------|
| Embankments | 25.2% | 3.38% | 71.43% |

There was some change to the Embankments this year with 25% deteriorating from last year and only 3% improving.

However, as the Average Condition graph below shows, the overall condition improved very slightly over last year, suggesting that the improved sections improved significantly and the deteriorated sections deteriorated slightly. The average condition over the last six years has remained very stable, showing only very minor fluctuations in either direction.





- Major Maintenance Required
- Backlog Maintenance Required
- Normal Maintenance
- ICM ZONE
- ICM SUB-ZONE

Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.

Condition data provided by ICM - Hyenson report.

Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology

Embankment Condition map.

2020-21

ICM Zone: Lower Waikato (western) Sub Zone Area (Labelled)




Scale at A4
 = 1:200,000

Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REO173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, howsoever, for any loss, damage, injury expenses (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology


Embankment Condition map.
2020-21
ICM Zone: Lower Waikato (eastern) Sub Zone Area (Labelled)



Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StateNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology


Embankment Condition map.
2020-21
ICM Zone: Lower Waikato (western)
Work Supervisor Area (Labelled)



Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



- Deteriorated
- Improved
- No Change
- ICM ZONE

Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hygiene report.
 Eagle Technology, LINZ, StateNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology

Embankment Condition Change map.

2020-21


ICM Zone: Lower Waikato (western)



Created by: AJH
 Date: 27/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. PACS Management Boundaries Data.
 Condition data provided by ICM - Hypon report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology

Embankment Condition Change map.
2020-21
ICM Zone: Lower Waikato (eastern)



Created by: AJH
 Date: 27/05/2021
 Version: 1
 File: REQ773154




DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.

A list of embankments in a poor condition is shown below. These assets should be prioritised in any upcoming capital works programme, as the integrity of the stopbanks could be compromised.


| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change | Length (km) | Current Inspection Notes |
|---------------------------------------|------------------|-------------------------|-------------------------|------------------|-------------|--|
| Tickles SB | Stopbank | 2 | 4 | 2 | 1.59 | Hasn't really improved by itself |
| Te Kohanga Major-Eastern Section 3 SB | Stopbank | 2 | 4 | 2 | 0.556 | Full of bull holes, bank is backup for breach of other bank, whole place needs looking at. |
| Pouarauroa Stream Comp 1 LB SB | Stopbank | 2 | 4 | 2 | 0.806 | Needs renewal |
| Pouarauroa Stream Comp 1 RB SB | Stopbank | | 4 | 2 | 0.868 | Bank needs major work |
| Pouarauroa Stream Comp 1 Spillway LB | Spillway | 2 | 4 | 2 | 0.392 | Can't see much of bank under long grass |

4.4 Main Channels and Tributaries

134km of Main channels and tributaries are being reported on this year, however only one Main Channel was inspected this year and it was rated at condition 3. The tributaries were found to all be in an average to good condition with erosion and vegetation being the most common issues in the inspection notes.




| | Deteriorated | Improved | No Change |
|--------------|--------------|----------|-----------|
| Main Channel | 100% | 0% | 0% |
| Tributary | 7% | 52% | 41% |



Main channels show a stable line across the previous 5 years, with a swing towards deterioration this year. Tributaries are show a slow improvement over the last 6 years. There should be some investigation as to what is being done differently between the two asset types in order to explain this difference.

4.5 Other Assets


All assets that fall into the “Other” category were found to be in average to good condition this year.



| | Deteriorated | Improved | No Change |
|--------------|--------------|----------|-----------|
| Other Assets | 20% | 18% | 61% |

The almost even deterioration to improvement ratio suggests that current maintenance efforts are keeping pace with the natural decline in condition over time.

| | C2 | C3 |
|-------------------------|----|----|
| Boat Ramp | 1 | |
| Bridge: Concrete | 6 | |
| Bunds | | 1 |
| Canal | 1 | |
| Control Gate | | 3 |
| Culvert: Conventional | 8 | 2 |
| Groynes | | 1 |
| Pole | 50 | 2 |
| Pumpstation: Archimedes | 1 | 1 |
| Weir: Concrete | 1 | |
| Weir: Rock | 11 | 5 |
| Weir: Timber | 2 | |




The condition of Other Assets has remained exceptionally stable over the last 6 years.

5 Franklin

5.1 Floodgates

There is one Floodgate in Franklin, Kaawa Twin Box Floodgate; both the floodgate and all its components are graded at condition 2. This is exactly the same score as last year, showing neither improvement nor deterioration.


Despite the name “Kaawa Twin Box Floodgate” this asset only has a single pipe and flapvalve. ConQuest action 342126 describes this asset as having been ripped out and replaced by the Farmer occupying the area, hence the name confusion. It is unclear if this issue has ever been resolved.



Please note there are some gaps in the available data so parts of this trend graph have been interpolated. The discovery of the unauthorised refurbishment appears to have been April 2019 which is likely why the condition has improved – it is no longer the same asset it was.

5.2 Embankments

There are two Embankments in Franklin, totalling 4.95km. All of this is graded at condition 3, both having deteriorated from last year. The inspection notes don't give any particular reason for the C3 score.




The overall trend of embankments in Franklin is one of improvement, despite this year's decline.


6 Waikato Central

6.1 Pumpstations

There are 2 Pumpstations in Waikato Central and both were graded as Condition 2, in good condition overall.



| Row Labels | No Change | Deteriorated |
|--------------|-----------|--------------|
| PS Component | 79.3% | 20.7% |
| Pumpstation | 100.0% | 0.0% |




Aside from the 2017/18 fluctuation, the overall condition of these two Pumpstations has been stable.

The only component in poor condition is the Manor Park PS Screen, however this was determined by the inspector not to impact the overall condition of the pumpstation. This screen should be replaced as soon as practicable.

| Asset ID | Description | Type description | Previous Year Condition | Current Condition Score | Condition Change | Current Inspection Notes |
|----------|------------------------|------------------|-------------------------|-------------------------|------------------|--------------------------|
| 44325 | Manor Park PS - Screen | Screen: Bar | 2 | 4 | 2 | Rusted |


6.2 Floodgates

There are 8 floodgates in Waikato Central, all (including their components) were found to be in average to good condition with very little change from last year.



| Row Labels | No Change | Deteriorated |
|--------------|-----------|--------------|
| FG Component | 95.1% | 4.9% |
| Floodgate | 87.5% | 12.5% |


The only components that deteriorated were an inlet and an outlet, however both were still found to be condition 3.



The trend is exceptionally stable over the last 6 years, with almost no fluctuation. This suggests that maintenance is keeping pace with natural deterioration.

6.3 Other Assets

All assets categorised as Other were found to be condition 2, with no changes recorded from last year. Inspection notes list vegetation and lack of access/visibility as the main concerns. The trend is very stable over the last 6 years.




| | C2 |
|-----------------------|----|
| Barrel: Pipe | 5 |
| Culvert: Conventional | 4 |
| Drop Structures | 7 |
| Manhole | 4 |
| Grand Total | 20 |

7 Waihou

Combined maps for Waihou/Piako assets are available in section 9.


7.1 Pumpstations

Nearly 97% of the 19 pumpstations inspected were considered to be in average to good condition, with one Pumpstation (Roger Harris (H Drain) PS) being in a poor condition. This was scored a C4 because of an end-of-life switchboard which is already in the process of being replaced.



| Row Labels | No Change | Deteriorated | Improved |
|--------------|-----------|--------------|----------|
| PS Component | 87.1% | 10.1% | 2.8% |
| Pumpstation | 42.1% | 57.9% | 0.0% |

Buildings, Inlets and Screens were the components that deteriorated the most, while Diesel storage tanks and Pumps improved the most.




After a very stable run, this year the average condition has deteriorated.

This is important to note – the overall picture presented in this section of the report is generally good, with few assets in poor condition, but the average condition shifted considerably from last year, suggesting that there was a large proportion deteriorating to an average condition. This could either be a result of the different scoring systems or it could indicate a genuine degradation in asset condition, in which case this should be monitored closely so that there is no sudden mass degradation to C4.


| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change | Current Notes | Inspection |
|--|---------------------------|-------------------------|-------------------------|------------------|-------------------------|------------|
| 15) Roger Harris (H Drain) Pumpstation | Pumpstation: Siphon Flood | 2 | 4 | 2 | Switchboard end of life | |
| Components: | | | | | | |
| Roger Harris (H drain) PS - Switchboard and Controls | Switchboard and Controls | 3 | 4 | 1 | End of life unsafe | |
| Kurere (Komata North) PS - Screen | Screen: Bar | 2 | 4 | 2 | Rusted | |

7.2 Floodgates

68 floodgates were inspected this year, with 90% found to be in average to good condition. Where Floodgates are in poor condition, it is most commonly because of issues with Inlets and Outlets. Inlets and Outlets were also the most likely component type as well as the most likely to have deteriorated. Chain and Winch Lifting Gear also showed a high level of deterioration. Service beams were the most improved asset type, possibly reflecting an increased Organisational focus on Health and Safety.



| Row Labels | No Change | Deteriorated | Improved |
|--------------|-----------|--------------|----------|
| FG Component | 76% | 18% | 5% |
| Floodgate | 51% | 49% | 0% |




Overall Condition for Floodgates has remained stable over time, with a moderate swing towards deterioration this year.

| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change Raw | Current Inspection Notes |
|------------------------------------|-------------------------|-------------------------|-------------------------|----------------------|---------------------------------------|
| 09) Torrs Floodgate | Floodgate: Diaphragm | 2 | 4 | 2 | See outlet comments |
| 09) Huirau Road Floodgate | Floodgate: Conventional | 2 | 4 | 2 | Outlet retaining failed |
| 6) Bond Road Floodgate | Floodgate: Conventional | 2 | 4 | 2 | Outlet retaining failed |
| 4) Central Drain Floodgate | Floodgate: Diaphragm | 2 | 4 | 2 | Retaining issues at inlet and outlet |
| 08) Alexanders Floodgate | Floodgate: Conventional | 3 | 4 | 1 | Inlet retaining failing |
| 09) Peartree Floodgate | Floodgate: Conventional | 2 | 4 | 2 | Inlet retaining failed |
| 09) Buchanans Floodgate | Floodgate: Conventional | 2 | 4 | 2 | Inlet issues |
| Components: | | | | | |
| Low Avenue FG - Lifting Gear Inlet | Lifting Gear: Hydraulic | 2 | 4 | 2 | Cylinder rusted out |
| Torrs FG - Flapvalve | Valve: Flap Rectangular | 2 | 4 | 2 | Rusty hangers and weathered timber |
| Torrs FG - Outlet Structure | Outlet Structure | 3 | 4 | 1 | Retaining failed |
| Huirau Road FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Retaining walls failed |
| Captain Cook FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Retaining failed |
| Netherton FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Unserviceable |
| Golf Course FG - Flapvalve | Valve: Flap Rectangular | 2 | 4 | 2 | Very Worn |
| Bond Road FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Retaining failed |
| Matatoki FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Retaining and concrete repairs needed |
| Central Drain FG - Inlet Structure | Inlet Structure | 2 | 4 | 2 | Retaining failed |
| Alexanders FG - Inlet Structure | Inlet Structure | 2 | 4 | 2 | Retaining failing |


| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change Raw | Current Inspection Notes |
|-------------------------------------|-------------------------|-------------------------|-------------------------|----------------------|--------------------------------------|
| Peartree FG - Inlet Structure | Inlet Structure | 2 | 4 | 2 | Retaining failed |
| Rangiora Link FG - Flapvalve 1 | Valve: Flap Rectangular | 3 | 4 | 1 | End of life |
| Paeroa Main Drain FG - Service Beam | Service Beam | 3 | 4 | 1 | Shakes violently when you walk on it |
| Buchanans FG - Inlet Structure | Inlet Structure | 2 | 4 | 2 | Retaining failed |

7.3 Embankments

All the 164km of embankments inspected this year has been found to be in average to very good condition, with 97.5% being in good or very good condition. Less than 3% has deteriorated since last year and the most common defect listed is overgrown grass.




| | Deteriorated | Improved | No Change |
|--------------------|--------------|----------|-----------|
| Sum of Length (km) | 2.87% | 0.52% | 96.62% |




There has been very little change in the Embankment Average Condition over time. This suggests that the maintenance programs in place to look after these embankments are working well.

7.4 Main Channels and Tributaries

462km of Main Channels and Tributaries were inspected this year. All Main Channels were graded at condition 2, and all tributaries were found to be in good or very good condition. Both Main Channels and Tributaries show significant improvement over last year, possibly reflecting the calmer weather conditions this year.



| | Improved | No Change |
|--------------|----------|-----------|
| Main Channel | 67% | 33% |
| Tributary | 61% | 39% |




Both Main Channels and Tributaries are showing improvement over time, work should be done to ascertain why, and how we can replicate this elsewhere.

7.5 Other Assets

All assets falling into the “Other” category were graded at condition 2, with very little change from last year. The inspection notes show some vegetation concerns but no other issues.


| | Deteriorated | Improved | No Change |
|--------------|--------------|----------|-----------|
| Other Assets | 3% | 7% | 90% |



The average condition is slowly improving over time.

| | 2 |
|--------------------------------------|-----------|
| Bank Revetment: Fabriform | 1 |
| Bank Revetment: Retaining Structures | 16 |
| Barrel: Pipe | 2 |
| Culvert: Conventional | 11 |
| Debris Traps | 5 |
| Fence: Conventional | 4 |
| Gradient Control Structure | 8 |
| Indigenous Planting | 1 |
| Indigenous Scrub | 2 |
| Inlet/Outlet Structures | 1 |
| Lined Channel: Concrete | 2 |
| Lined Channel: Fabriform | 1 |
| Lined Channel: Pre-Cast Concrete | 2 |
| Lined Channel: Rip Rap | 1 |
| Outlet Structure | 3 |
| Poplar | 1 |
| Rip-Rap | 7 |
| Sediment Ponds | 1 |
| Stoplog: Temporary | 3 |
| Weir: Concrete | 1 |
| Weir: Rock | 1 |
| Grand Total | 74 |

8 Waihou/Piako Maps



Acknowledgements and Disclaimers:
 © Waikato Regional Council 2004. RACS Management Boundaries Data.

Condition data provided by ICM - Hyperion report.

Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology

Pumpstation Condition map.

2020-21

ICM Zone: Waihou-Piako
 Sub Zone Area (labelled)


0 1.5 3 4.5 6 7.5 km

Scale at A4
 = 1:200,000

Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REG173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management
 Boundaries Data.

Condition data provided by ICM - Hyperion report.

Eagle Technology, LINZ, StabiNZ, NIWA, Natural Earth,
 © OpenStreetMap contributors, LINZ, Eagle Technology

Pumpstation Condition map.

2020-21

**ICM Zone: Waihou-Piako
 Work Supervisor Area (labelled)**




Scale at A4
 = 1:200,000

Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology


Pumpstation Condition Change map.
2020-21
ICM Zone: Waihou-Piako



Created by: AJH
 Date: 27/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise howsoever, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology


Floodgate Condition map.
2020-21
ICM Zone: Waihou-Piako Sub Zone Area (labelled)



Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. FIACS Management
 Boundaries Data.

Condition data provided by ICM - Hyperion report.

Eagle Technology, LINZ, StateNZ, NIWA, Natural Earth,
 © OpenStreetMap contributors, LINZ, Eagle Technology

Floodgate Condition map.

2020-21

ICM Zone: Waihou-Piako
 Work Supervisor Area (labelled)




Scale at A4
 = 1:200,000

Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114_



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise
 however, for any loss, damage, injury expenses (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hypanon report.
 Eagle Technology, LINZ, StataNZ, NWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology


Floodgate Condition Change map.
2020-21
ICM Zone: Waihou-Piako



Created by: AJH
 Date: 27/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology


Embankment Condition map.
2020-21
ICM Zone: Waihou-Piako
Sub Zone Area (Labelled)



Created by: AJH
 Date: 17/05/2021
 Version: 1
 File: REQ173114



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, howsoever, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology

Embankment Condition Change map.
2020-21
ICM Zone: Waihou-Piako

0 1.5 3 4.5 6 7.5 km
 Scale at A4 = 1:200,000

Created by: AJH
 Date: 27/05/2021
 Version: 1
 File: REQ173114

Waikato
 REGIONAL COUNCIL
 Te Kaitiaki a Māori o Waikato

DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the accuracy of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise howsoever, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.


9 Piako

Combined maps for Waihou/Piako assets are available in section 9

9.1 Pumpstations


28 Pumpstations were inspected this year, with 68% of them found to be in an average to good condition, with the remaining 32% (or 9 Pumpstations) in poor condition.

Those Pumpstations in poor condition, are most likely to be in poor condition due to issues with Inlets, Outlets, Pipework, Pumps and Switchboards.



| | No Change | Deteriorated | Improved |
|--------------|-----------|--------------|----------|
| PS Component | 74% | 24% | 2% |
| Pumpstation | 21% | 79% | 0% |

100% of Surge Chambers and Hydraulic lifting gear, and 63% of inlets deteriorated between last year and this year.



This year shows a significant swing towards deterioration in the average condition. This could be due to the new condition scoring criteria, represent a genuine deterioration in the asset base, or be a combination of the two.


A list of both parent and child assets in a poor condition is shown below. These assets should be prioritised in any upcoming capital works programme as they present an urgent risk to the safe operating of the assets.

| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change | Current Inspection Notes |
|---|---------------------------|-------------------------|-------------------------|------------------|--|
| 13) Paul Leonard Pumpstation | Pumpstation: Throughbank | 2 | 4 | 2 | See inlet and outlet comments |
| 10) Johnstones Pumpstation | Pumpstation: Throughbank | 2 | 4 | 2 | See other comments |
| 17) Ngarua Central Pumpstation | Pumpstation: Throughbank | 2 | 4 | 2 | See inlet comments |
| 17) Prices Pumpstation | Pumpstation: Throughbank | 2 | 4 | 2 | See outlet comment |
| 18) Mangawhero Pumpstation Piako | Pumpstation: Throughbank | 2 | 4 | 2 | See inlet comments |
| 19) Waikaka North Pumpstation | Pumpstation: Throughbank | 2 | 4 | 2 | See inlet comments |
| 20) Waikaka South Pumpstation / Floodgate | Pumpstation: Throughbank | 2 | 4 | 2 | See other comments |
| 22) Kerepehi Extension Pumpstation | Pumpstation: Throughbank | 2 | 4 | 2 | See outlet comments |
| 28) Awaiti South Pumpstation | Pumpstation: Throughbank | 2 | 4 | 2 | See inlet comments |
| Components | | | | | |
| Appletree PS – Pipework | Pipework | 2 | 4 | 2 | Pump 2 pipe is cracked open and water squirts out when pump runs |
| Rawe Rawe PS - Inlet Structure | Pumpstation Inlet Bay | 2 | 4 | 2 | Timber retaining rotten |
| Paul Leonard PS - Outfall Structure | Outlet Structure | 2 | 4 | 2 | Timber retaining is at EOL |
| Paul Leonard PS - Inlet Structure | Pumpstation Inlet Bay | 2 | 4 | 2 | Timber retaining at EOL |
| Paul Leonard PS - Pipework | Pipework | 2 | 4 | 2 | Pipe at EOL |
| Johnstones PS - Pump Building | Building: Corrugated Iron | 2 | 4 | 2 | Major leaning |
| Johnstones PS - Outfall Structure | Outlet Structure | 2 | 4 | 2 | Retaining end of life |


| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change | Current Inspection Notes |
|---|----------------------------|-------------------------|-------------------------|------------------|---|
| Ngarua Central PS - Inlet Structure | Pumpstation Inlet Bay | 2 | 4 | 2 | Timber retaining has rotted and failed |
| Prices PS - Outfall Structure | Outlet Structure | 2 | 4 | 2 | No retaining. Timber access plank with no handrails is unsafe |
| Mangawhero PS - Inlet Structure | Pumpstation Inlet Bay | 2 | 4 | 2 | Timber retainer rotten and failing |
| Waikaka North PS - Inlet Structure | Pumpstation Inlet Bay | 3 | 4 | 1 | Retaining wall at EOL |
| Reservoir Canal PS / FG - Switchboards and Controls | Switchboard and Controls | 2 | 5 | 3 | Very old fire risk and resilience risk |
| Kerepehi Extension PS - Outfall Structure | Outlet Structure | 2 | 4 | 2 | Retaining rotten and erosion |
| Poulgrains PS - Switchboards and Controls | Switchboard and Controls | 2 | 4 | 2 | Very old, fire risk |
| Wani Road PS - Pump | Pump: Axial Vertical Shaft | 2 | 5 | 3 | Pump end of life |
| Wani Road PS - Outfall Structure | Outlet Structure | 2 | 4 | 2 | Needs wing walls and ramp converting to steps |
| Wani Road PS - Pipework | Pipework | 2 | 5 | 3 | Pipe end of life |
| Awaiti South PS - Screen | Screen: Bar | 2 | 4 | 2 | Very rusty |
| Awaiti South PS - Inlet Structure | Pumpstation Inlet Bay | 2 | 4 | 2 | Timber retaining rotting bowing and failing |

9.2 Floodgates

73% of the 60 floodgates are in average to good condition, meaning there are 16 floodgates that are condition 4 or 5. Where floodgates are in poor condition, it is frequently due to poor condition Inlets and Outlets; there are 6 inlets and 16 outlets in poor condition.



Percentage of FG Components at each Condition




| | No Change | Deteriorated | Improved |
|--------------|-----------|--------------|----------|
| FG Component | 71% | 27% | 2% |
| Floodgate | 47% | 53% | 0% |

100% of Round Flap Valves and Bank Revetment (Piles) had deteriorated, along with 49% of outlets and 38% of Rack and Pinion lifting gear.

Box Barrels and Rack and Pinion lifting gear showed the greatest improvements at 29% and 25% respectively.

The fact that Rack and Pinion lifting gear showed such high deterioration and improvement suggests a large discrepancy between the old and new condition assessment standards.

Floodgate Average Condition Over Time




Similar to the Piako Pumpstations, this year shows a significant swing towards deterioration in the average condition. This could be due to the new condition scoring criteria, represent a genuine deterioration in the asset base, or be a combination of the two.

| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change | Current Inspection Notes |
|--|--------------------------------------|-------------------------|-------------------------|------------------|---|
| 3) Reserve Floodgate | Floodgate: Conventional | 2 | 4 | 2 | See outlet notes |
| 04) Marshalls Floodgate | Floodgate: Conventional | 3 | 4 | 1 | See other comments on assets |
| 03) Pipiroa West Floodgate | Floodgate: Conventional | 2 | 4 | 2 | See outlet comments |
| 04) Settlers Floodgate | Floodgate: Conventional | 2 | 4 | 2 | See notes for other individual assets |
| 06) Duck Creek Floodgate | Floodgate: Conventional | 2 | 4 | 2 | See other comments on individual assets |
| 08) Pauls Wharf Floodgate | Floodgate: Conventional | 3 | 5 | 2 | Asset being decommissioned |
| 10) Paul Leonard Floodgate | Floodgate: Conventional | 2 | 4 | 2 | See outlet comments |
| 11) Ngatea Township Floodgate | Floodgate: Diaphragm | 2 | 4 | 2 | See note on inlet concrete damage |
| 04) Limeworks Floodgate | Floodgate: Conventional | 2 | 4 | 2 | See issues on individual assets |
| 06) Phillips Road Twin Floodgate | Floodgate: Box | 2 | 4 | 2 | See inlet and outlet comments |
| 10) Stitchburys Floodgate | Floodgate: Conventional | 2 | 4 | 2 | See inlet comments |
| 10) Prices Single Floodgate | Floodgate: Conventional | 2 | 4 | 2 | See outlet comments |
| 12) No.10 Floodgate | Floodgate: Box | 2 | 4 | 2 | See outlet and inlet comments |
| 19) DOC Floodgate | Floodgate: Box | 2 | 5 | 3 | Outlet failed |
| 15) Haughs Road Floodgate | Floodgate: Conventional | 2 | 4 | 2 | See comments on inlet and outlet |
| 03) Pouarua Floodgate | Floodgate: Box | 2 | 4 | 2 | See outlet comments |
| Components | | | | | |
| Reserve FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Silted up, retaining failed, access issues |
| Reserve FG - Lifting Gear Outlet | Lifting Gear: Chain and Winch | 2 | 4 | 2 | Chain end of life |
| Marshalls FG - Outlet Structure | Outlet Structure | 3 | 4 | 1 | Wing wall crack. Retaining knackered and erosion close to stop bank |
| Pipiroa West FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Retaining knackered erosion getting close to stop bank |
| Settlers FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Retaining knackered |
| Duck Creek FG - Outlet Timber Retaining Wall | Bank Revetment: Retaining Structures | 2 | 4 | 2 | Retaining structure knackered |
| Pauls Wharf FG - Outlet Structure | Outlet Structure | 3 | 4 | 1 | Retaining knackered |
| Pauls Wharf FG - Flapvalve | Valve: Flap Rectangular | 2 | 5 | 3 | . |
| Pauls Wharf FG - Lifting Gear Outlet | Lifting Gear: Chain and Winch | 2 | 5 | 3 | Missing |
| Paul Leonard FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Earth collapse very close to stop bank |
| Ngatea Township FG - Inlet Structure | Inlet Structure | 2 | 4 | 2 | Concrete damage at flap sealing face big job to fix |


| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change | Current Inspection Notes |
|--|-------------------------------|-------------------------|-------------------------|------------------|--|
| | | | | | but needs doing before gets worse |
| Pipiroa East FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Outlet retaining wall collapsing |
| Limeworks FG - Inlet Structure | Inlet Structure | 1 | 4 | 3 | Inlet retainer is holding up stop bank and very weak bending a lot |
| Limeworks FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Outlet retainer has a snapped whaler |
| James FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Retaining walls knackered |
| Blakes FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Outlet retaining failing |
| Phillips Road Twin FG - Inlet Structure | Inlet Structure | 2 | 4 | 2 | Retaining knackered |
| Phillips Road Twin FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Retaining knackered erosion very close to stop bank |
| Stitchburys FG - Inlet Structure | Inlet Structure | 2 | 4 | 2 | Some cracks in concrete structure and timber retaining wall knackered |
| Prices Single FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Erosion very close to stop bank. No retaining present at all |
| No.10 FG - Inlet Structure | Inlet Structure | 2 | 4 | 2 | Retaining wall knackered |
| No.10 FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Retaining failing and concrete cracks |
| No.10 FG - Sluice Gate 1 | Valve: Sluice Gate | 2 | 5 | 3 | Concrete sluice |
| No.10 FG - Sluice Gate 2 | Valve: Sluice Gate | 2 | 5 | 3 | Concrete sluice |
| No.10 FG - Sluice Gate 3 | Valve: Sluice Gate | 2 | 5 | 3 | Concrete sluice |
| TO BE DISPOSED - No.10 FG - Lifting Gear Inlet 1 | Lifting Gear: Rack and Pinion | 2 | 5 | 3 | End of life |
| TO BE DISPOSED - No.10 FG - Lifting Gear Inlet 2 | Lifting Gear: Rack and Pinion | 2 | 5 | 3 | End of life |
| TO BE DISPOSED - No.10 FG - Lifting Gear Inlet 3 | Lifting Gear: Rack and Pinion | 2 | 5 | 3 | End of life |
| DOC FG - Outlet Structure | Outlet Structure | 2 | 5 | 3 | Completely failed |
| DOC FG - Pipe | Barrel: Box | 2 | 4 | 2 | Pipe could be wooden stave. Exposed and 1/2 blocked |
| Haughs Road FG - Inlet Structure | Inlet Structure | 2 | 4 | 2 | Retaining wall end of life |
| Haughs Road FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Channel blocked up with vegetation needs a good clean out and understand how exposed the ends of the stop bank are |
| Carters Block FG - Sluice Gate 2 | Valve: Sluice Gate | 2 | 5 | 3 | To be replaced this year |
| Carters Block FG - Sluice Gate 1 | Valve: Sluice Gate | 2 | 5 | 3 | To be replaced this year |
| Pouarua FG - Outlet Structure | Outlet Structure | 2 | 4 | 2 | Retaining failed |

9.3 Embankments

94.6% of the 133km of embankments surveyed in Piako are in average to very good condition, with 85.5% in good or very good condition. Vegetation was the concern most mentioned in the inspection notes.



| | Deteriorated | Improved | No Change |
|--------------------|--------------|----------|-----------|
| Sum of Length (km) | 14.48% | 1.24% | 84.28% |




The trend is for a slow improvement in average condition; there is a very small rise this year but it is statistically negligible. Maintenance programs for stopbanks appear to be generally successful.

As seen below, Awaiti: Reservoir Canal Road to Tee Head SB is the only stopbank in poor condition currently. This has a ConQuest action for an upgrade scheduled for Summer 21/22, so the issue is being actively managed.

| Description | Type description | Previous Year Condition | Current Condition Score | Condition Change | Length (km) | Current Inspection Notes |
|---|------------------|-------------------------|-------------------------|------------------|-------------|---|
| Awaiti: Reservoir Canal Road to Tee Head SB | Stopbank | 2 | 4 | 2 | 8.5 | No fence along entirety of channel, river side of bank quite damaged, |

9.4 Main Channels and Tributaries

362km of Main channels and Tributaries were inspected this year, with all of it being in an average to good condition. Inspection notes mention the need for dredging of main channels and erosion as the main concerns.




| Row Labels | Deteriorated | Improved | No Change |
|--------------|--------------|----------|-----------|
| Main Channel | 26% | 0% | 74% |
| Tributary | 2% | 21% | 77% |


There is not sufficient data going back through the years to produce any useful trend information.

9.5 Other

Of the 19 assets that fell into the “Other” category, all were found to be in average to very good condition with very minimal deterioration.



| | Deteriorated | Improved | No Change |
|--------------|--------------|----------|-----------|
| Other Assets | 11% | 5% | 84% |




| Row Labels | 0 | 1 | 2 | 3 |
|-----------------------|---|---|----|---|
| Bank Revetment: Piles | | | 2 | |
| Bridge: Timber/Steel | 1 | | 2 | |
| Canal | | | 3 | 1 |
| Culvert: Conventional | | | 5 | |
| Groynes | | 1 | 1 | |
| Rip-Rap | | | 4 | |
| Grand Total | 1 | 1 | 17 | 1 |

10 Thames Valley

10.1 Pumpstations

There is one Pumpstation in Thames Valley and it was graded as a condition 2 with no change on last year. All components were also graded at condition 2, with some components showing improvement.

| | No Change | Improved |
|--------------|-----------|----------|
| PS Component | 93% | 7% |
| Pumpstation | 100% | 0% |




Pumpstation average condition has remained absolutely stable over time, indicating that the maintenance on this pumpstation being done regularly and to a high standard. Due to the fact it is only one station though it is unlikely to be something that can be applied more broadly.

10.2 Floodgates


There are 11 floodgates in Thames Valley; 73% are in an average to good condition, with 3 in a poor or very poor condition.

The floodgates in a poor condition mostly had issues with Inlets and Outlets, these component asset types also showed the greatest deterioration. These asset types, along with Rack and Pinion lifting gear also showed the greatest deterioration since last year.

Percentage of Floodgates at each Condition




Percentage of FG Components at each Condition



| | No Change | Deteriorated | Improved |
|--------------|-----------|--------------|----------|
| FG Component | 52% | 40% | 8% |
| Floodgate | 18% | 55% | 27% |

The most improved asset type was Chain and Winch lifting gear.




Floodgate Average condition has been deteriorating steadily over the last six years. This, combined with the 55% deterioration this year suggests that there may be a large number of assets needing major attention in Thames Valley in the next 10 years. To avert this, the current maintenance schedule should be reviewed for effectiveness.

| Asset ID | Description | Type description | Previous Year Condition | Current Condition Score | Condition Change | Current Inspection Notes |
|--------------------|--|-------------------------------|-------------------------|-------------------------|------------------|--|
| 23718 | Whakahoro Road West R1 Floodgate | Floodgate: Conventional | 4 | 5 | 1 | Major issues |
| 25226 | Zig Zag Right Bank Floodgate 3 | Floodgate: Conventional | 2 | 4 | 2 | Inlet retaining has failed |
| 27475 | Moore-Hopper Floodgate | Floodgate: Conventional | 3 | 4 | 1 | Outlet issues |
| Components: | | | | | | |
| 14820 | Whakahoro Road FG - Outlet Structure | Outlet Structure | 2 | 5 | 3 | Stop bank collapsing above asset |
| 76728 | Whakahoro Road FG - Inlet Structure | Inlet Structure | 3 | 4 | 1 | Retaining failed and inlet platform failed |
| 76729 | Whakahoro Road FG - Sluice Gate 1 | Valve: Sluice Gate | 4 | 5 | 1 | Dangerous |
| 76730 | Whakahoro Road FG - Sluice Gate 2 | Valve: Sluice Gate | 4 | 5 | 1 | Dangerous |
| 76731 | Whakahoro Road FG - Inlet Lifting Gear 1 & 2 | Lifting Gear: Rack and Pinion | 4 | 5 | 1 | Dangerous |
| 79075 | Whakahoro Road FG - Service Beam | Service Beam | 2 | 5 | 3 | Needs a service beam installed |
| 14825 | Zig Zag Right Bank FG 3 - Inlet Structure | Inlet Structure | 2 | 4 | 2 | Retaining failed |
| 14829 | Moore-Hopper FG - Outlet Structure | Outlet Structure | 3 | 4 | 1 | Major issue with retaining |

10.3 Embankments


There are 4km of Embankments in Thames Valley and all are Condition 2 with no change from last year.



Average condition has been mostly stable with some fluctuations, suggesting the stopbank maintenance is keeping pace with any degradation that is occurring. The patterned bar denotes an interpolated value.


10.4 Other

There are 28 assets that fall into the “Other” category, of these all are in an average to very good condition, with 89% in good or very good condition.



| | Deteriorated | Improved | No Change |
|--------------|--------------|----------|-----------|
| Other Assets | 11% | 11% | 76% |

The even deterioration to improvement ratio suggests that current maintenance efforts are keeping pace with the natural decline in condition over time.




Average condition has been stable over time with almost no fluctuation.

| | 1 | 2 | 3 |
|--------------------------------------|---|----|---|
| Bank Revetment: Retaining Structures | 1 | 15 | 3 |
| Culvert: Conventional | | 1 | |
| Drop Structures | | 8 | |
| Grand Total | 1 | 24 | 3 |


11 Coromandel

11.1 Floodgates

All floodgates in Coromandel are in good or very good condition with very little change from last year.



| Row Labels | No Change | Improved |
|--------------|-----------|----------|
| FG Component | 82% | 18% |
| Floodgate | 100% | 0% |




The overall trend for Coromandel Floodgates is one of stability. Year on year there is little change in the condition of these assets and inspection notes typically describe few issues other than vegetation.

The maintenance in this area appears to be keeping pace with natural decline.

11.2 Embankments

There are 16 Embankments in Coromandel totalling 1.95km. These are all scored a 2 with no changes from last year.




Similar to Floodgates, Embankments in Coromandel show a trend of stability with very little change. The inspection notes for these assets show a variety of minor defects to be addressed.

11.3 Main Channels and Tributaries

All Main Channels and Tributaries in Coromandel were graded at condition 2. Inspection notes for Coromandel listed erosion control and vegetation as the most common issues to be addressed.


| | Improved | No Change |
|--------------|----------|-----------|
| Main Channel | 40% | 60% |
| Tributary | 73% | 27% |




There is a general trend of improvement in Coromandel’s main channels and tributaries. Work should be done to ascertain why, and how we can replicate this elsewhere.

11.4 Other Assets

All assets falling into the “Other” category are in good or very good condition, with the inspection notes listing vegetation control as the main concern.



| | Improved | No Change |
|--------------|----------|-----------|
| Other Assets | 11% | 89% |



The overall trend is very stable with no major fluctuations, improvements, or declines.


| | 1 | 2 |
|--------------------------------------|---|----|
| Bank Revetment: Retaining Structures | | 2 |
| Canal | 2 | 1 |
| Rip-Rap | 4 | 10 |
| Grand Total | 6 | 13 |

12 Lake Taupo


12.1 Floodgate

There were 2 floodgates that could not be inspected due to overgrown vegetation. All of the remaining floodgates and their components were graded as Condition 2.

| | No Change | Improved |
|--------------|-----------|----------|
| FG Component | 96% | 4% |
| Floodgate | 96% | 4% |



The trend for Floodgates is very stable with no major fluctuations.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.
 Condition data provided by ICM - Hyperion report.
 Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology


Floodgate Condition Change map.
2020-21
ICM Zone: Lake Taupo



Created by: AJH
 Date: 27/05/2021
 Version: 1
 File: REQ173114_



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in compiling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise howsoever, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.



Acknowledgements and Disclaimers
 © Waikato Regional Council 2004. RACS Management Boundaries Data.

Condition data provided by ICM - Hyperion report.

Eagle Technology, LINZ, StatsNZ, NIWA, Natural Earth, © OpenStreetMap contributors, LINZ, Eagle Technology

Floodgate Condition map.
2020-21
ICM Zone: Lake Taupo
Work Supervisor Area (labelled)



Scale at A4
 = 1:150,000

Created by: AJH
 Date: 17/05/2021
 Version: 1


File: REQ173114_



DISCLAIMER: While Waikato Regional Council has exercised all reasonable skill and care in controlling the contents of this information, Waikato Regional Council accepts no liability in contract, tort or otherwise, however, for any loss, damage, injury expense (whether direct, indirect or consequential) arising out of the provision of this information or its use by you.

12.2 Embankments


All Embankments are in average to good condition. Inspection notes were not available at the time of writing, so it is difficult to determine the most critical issues affecting these assets.



Change data and Maps are not available for these assets.


12.3 Main Channels and Tributaries

All main channels and tributaries are in an average to good condition. The inspection notes list erosion, blockages, and invasive willows as being of concern to these waterways.



All Tributaries were graded at Condition 2.


| | Deteriorated | Improved | No Change |
|--------------|--------------|----------|-----------|
| Main Channel | 14% | 0% | 86% |
| Tributary | 0% | 97% | 3% |




The trend for Main channels is for stability, whilst the tributaries are improving slightly.

12.4 Other Assets

All Other assets were found to be in average to good condition with vegetation control and sediment/silt build up being the main issues mentioned in the inspection notes.



| | Deteriorated | Improved | No Change |
|--------------|--------------|----------|-----------|
| Other Assets | 3% | 15% | 82% |



The average condition of the Other Assets is stable over the last six years.


| | 2 | 3 |
|-----------------------|-----------|----------|
| Canal | 1 | 1 |
| Culvert: Conventional | 2 | |
| Fence: Conventional | 1 | |
| Ford Crossing | 1 | |
| Groynes | 1 | |
| Inlet Structure | 1 | |
| Outlet Structure | 2 | |
| Rip-Rap | 22 | 1 |
| Sediment Ponds | | 1 |
| Weir: Rock | 1 | |
| Grand Total | 32 | 3 |

13 Waipa

13.1 Main Channels and Tributaries


There were no main channels inspected in Waipa this year, only tributaries. These were found to be in average to good condition with no changes from the previous year. The inspection notes mention some gorse removal being required.

There is insufficient data to generate a trend for Waipa Main Channels and Tributaries.



13.2 Other Assets

The only asset inspected this year was the Lake Rotokauri Weir, which was graded as Condition 2 with no change from last year. The inspection notes list a slight warp in the wooden structure as being of concern.



This trend is stable, changing little in the last 5 years.